



Mounting Instructions

1




Ⓐ = 2x
 NOTE: Screws go through from sunk hole

2




3




Ⓑ = 4x
 Ⓒ = 4x
 Ⓓ = 4x


4




4a



5



6



Ⓔ = 2x

Ⓕ = 2x

